


CAUTION: Improper assembly of the OBD2 diagnostic sensor plugs (bike side and relayed light harness side) can result in shorting out the bike relay between the battery and ECU.

- If you connect the OBD2 relayed harness plug into the OBD2 diagnostic sensor plug and hear a **buzzing sound**, separate/disconnect the OBD2 connectors **immediately!**
OBD2 diagnostic plug on bike side



Cyclops Adventure Sports is not responsible for customers who short out the bike relay because the brass prong entered the wrong power port.