



Shop Notes:

During our shop testing of the 1190/1290 LED headlight replacement kit we have on occasion received "Lamp Failure" warning messages from the motorcycles computer. The following are methods we have used to clear the computer of this message.

- Remove your positive and negative leads from the battery for at least 20 minutes.
- We have also cycled the motorcycle through 3 to 4 start and stop cycles with successful results

If you have any questions please feel free to contact us at 1-800-624-0278 or
info@cyclopsadventuresports.com

Thank You for your purchase from Cyclops.